

Kingsville Done Project
May 13, 1988

Kingsville Dome Project
May 13, 1988... Table of Contents
Introduction

KINGSVILLE DOME PROJECT
EXPANSION No. 1

**SUPPLEMENTARY TECHNICAL
REPORT**

May 13, 1988

TABLE OF CONTENTS

KINGSVILLE DOME PROJECT SUPPLEMENTARY TECHNICAL REPORT

EXPANSION NO. 1

TABLE OF CONTENTS

	PAGE
1.0 Introduction.....	1
2.0 Surface Owners.....	2
3.0 Mineral Owners.....	14
4.0 Permit Area Location.....	28
5.0 Permit Area Topography.....	30
6.0 Permit Area Geology and Hydrology.....	39
7.0 Tobin Map.....	42
8.0 Mine Plan.....	43
9.0 Regional Geology.....	44
10.0 Water Supply Wells.....	47
11.0 Excursion Prevention.....	66
12.0 Well Completion.....	67
13.0 Mechanical Integrity.....	68
14.0 Hydrologic Testing.....	69
15.0 Restoration.....	70
16.0 Closing.....	71
17.0 Production Facilities and Procedures.....	72

KINGSVILLE DOME PROJECT SUPPLEMENTARY TECHNICAL REPORT

EXPANSION NO. 1

LIST OF FIGURES

FIGURE	DESCRIPTION	PAGE
Figure 1	Landowners Map.....	2
Figure 2	Mineral Owners.....	14
Figure 3	Permit Area Location.....	29
Figure 4	Artificial Penetrations.....	31
Figure 5	Cross Section Key.....	40
Figure 6	Cross Section "A" to "A" Prime.....	41
Figure 7	Tobin Map.....	42
Figure 8	Mine Plan Schedule.....	43
Figure 9	Mine Plan Plan View.....	44
Figure 10	Water Supply Wells.....	48

KINGSVILLE DOME PROJECT SUPPLEMENTARY TECHNICAL REPORT

EXPANSION NO. 1

LIST OF TABLES

TABLES	DESCRIPTION	PAGE
TABLE 1	Fluid Handling Requirements.....	46
TABLE 2	Water Supply Wells.....	52

1.0 INTRODUCTION

1.0 INTRODUCTION

This application is being made to expand the permitted and exempted portion of the Kingsville Dome Project. The portion of the Goliad Aquifer which will be affected by the exemption, if granted:

1. does not currently serve as a source of drinking water for human consumption; and
2. will not in the future serve as a source of drinking water for human consumption because of its mineral production capacity and URI's control of the leases.

To avoid wasting time, URI has not duplicated all the information which was within the application for URO 2827. Where such redundancies occur, it was simply noted that the information remains unchanged from the original applications.